



U.S. Department
of Transportation
**Federal Aviation
Administration**

Engine and Propeller Directorate

New York Aircraft Certification Office
1600 Stewart Avenue
4th Floor Suite 410
Westbury, NY 11590
(516) 228-7300, Fax: (516) 794-5531

MAR 29 2010

Ms. Jeanette Krueger
Supervisor Quality Control
National Parachute Industries, Inc.
P.O. Box 245 78 White Rd. Ext.
Palenville, NY 12463

Subject: Technical Standard Order (TSO) Authorization > Reissuance

Dear Ms. Krueger:

This is in reply to your letter of March 15, 2010 requesting reissuance of the Technical Standard Order (TSO) authorization for the below noted assembly. This reissuance is necessary because of an address change only. Your new facility was evaluated and approved by the Manufacturing Inspection District Office (MIDO-42). Effective this date, you are authorized to identify the following assembly with the marking requirements defined in 14 CFR § 21.607(d) and in TSO-C23b

<u>Part Number:</u>	<u>Description:</u>
81001	General Assembly – Auxiliary Parachute

Your Quality Control System, as defined in your Quality Control Manual, *National Parachute Industries, inc. Quality Control Manual*, dated December 9, 2008 is considered satisfactory for production of these articles at your facility.


Any design change to this TSO article, or the non-TSO function contained within, must be forwarded to this office as outlined in 14 CFR § 21.611 with minor change submittal intervals not to exceed six months. Also, as recipient of this authorization, you are required to report any failure, malfunction, or defect relating to this authorization in accordance with the provisions of 14 CFR § 21.3.

This authorization is not transferable to another person and is effective until surrendered, withdrawn, or otherwise terminated by the Administrator.

Please note that technical data retained by the FAA may be subject to Freedom of Information Act (FOIA) requests. As such, this office will notify you of all such requests pertaining to your data and afford you the opportunity to defend the release of the data.

If you have any questions regarding this authorization, contact Mr. Richard Beckwith at 516-228-7306.

Sincerely,



Anthony Socias
Manager, New York Aircraft Certification Office

cc: AIR-140; MIDO-42